

VEHICLE INSPECTION REPORT

YA17SUH

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	16/07/2017	Colour	SILVER	Gearbox	MANUAL
Year	2017	VIN	XLRAEL1500L465411	Axle Combi	4x2
Mileage	275,292 Km Warranted	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	31/03/2027	Rear Doors	Roller
GVW	7500kg	Cab Type	DAY CAB	Tail Lift	Column


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Multiple Chips



2: Wing osf
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK